

TABLE II

SILVER SEVEN PARTS LIST

Resistors

R1	100k, pot, log taper
R2	100k
R3, 136	6.8k
R5	47k, 2W
R6	270k
R7	360 Ω
R8	47 Ω
R9	82k, 10W
R10, 118-120	1m
R12	18k, 7W
R13	24k, 7W
R14	5.1k, 5W
R15, 16	13k, 1W
R19	3.9k
R20, 22, 25, 28, 31, 34, 37, 40, 44, 47, 50, 53, 56, 59, 133	6.8k, 2W
R21, 23, 26, 29, 32, 35, 38, 41, 45, 49, 51, 54, 57, 60	10 Ω , 5W
R24, 27, 30, 33, 36, 39, 42, 46, 48, 52, 55, 58, 61	100 Ω , 5W
R62	5 Ω , 5W
R63	3.3k, 2W
R64	1.1k, 5W
R69, 127	Glo-Bar Varistor
R70	3.9m
R71	1 Ω , 5W, 10%
R72, 111	680 Ω , 2W
R74-77, 123	220k, 2W
R79	.25 Ω , 5W
R80-86	470k, 1/2 W
R88, 115	10k, 1/4 W
R89	2k, 1/4 W
R90	270k, 1/4 W
R91	130 Ω , 2W
R93	200 Ω
R106	10m, 1/4 W
R112	.3 Ω , 25W
R114	100k, 1/4 W
R116	3.6k
R117	1.5k, 1W
R121	200k
R122	9.1k
R124	100
R125	220 Ω , 2W
R126	20 Ω , 2W
R128	150k, 1/4 W, 1%
R129	78.7k, 1/4 W, 1% (selected for 320V DC out)
R130	100k, 1/4 W, 1%
R131	10k, bias, pot WW
R132	1k
R137	91 Ω
R138	1 Ω , 5W, 10%

Capacitors

C1	1 μ F, 425V, WonderCap
C2	22pF
C4	25, 150V
C5, 14, 68	50, 450V

Continued 