



Arrows indicate Wiper movement for clockwise rotation of control.

Fig. 1. Circuit diagram of the Portable Oscilloscope Model OS-1

